



**Note:** After any field seam is completed, it must be probed to ensure that a secure weld has been made.

REVISED: N/A	TPO GENERAL DETAIL
PREVIOUS: 02/10/2025	FIELD SEAMING
SCALE: NONE	NEW CONSTRUCTION OR RE-ROOF