



Note: After any field seam is completed, it must be probed to ensure that a secure weld has been made.

REVISED:	10/03/17	GENERAL DETAIL
PREVIOUS:	10/13/16	FIELD SEAMING
SCALE:	NONE	NEW CONSTRUCTION OR RE-ROOF