



Note 1: Precaution must be taken to ensure that all wall-to-deck transitions are sealed.

Note 2: Termination Bar support bracket shall be used to support the membrane until the Duro-Last sealant cures. Do not fasten the support bracket.

Note 3: All field welds shall be a minimum of 1-1/2 inches wide.

Note 4: Refer to specifications for vapor barrier, insulation and cover board requirements.

REVISED:	11/07/17	DRAINAGE DETAIL FOR MECHANICALLY FASTENED SYSTEMS
PREVIOUS:	07/28/17	CLOSED-END MEMBRANE SCUPPER
SCALE:	NONE	NEW CONSTRUCTION OR RE-ROOF